

Technical Support Bulletin

TSB-1311

IntelliGuide v23/ v60 LED PCBA Replacement

Rev A

Product(s) Affected: IntelliGuide v23 and v60 products

Risk	Repair Method		
☐ Human Safety - personal injury may occur	☑ Repair On Tool		
\square Tool Safety - tool damage may occur	☐ Repair Off Tool		
☑ Product Safety - product damage may occur	☐ Repair Center		
\square No Safety Risk	☐ No Repair Required		
Priority	Parts Disposition		
\square Urgent - Immediate Proactive Action	☑ Return Old Parts for Analysis		
Required			
☐ Next Visit - Prompt Action Required	☐ Return Old Parts for Repair		
□ As Required - On Customer Request	☐ Dispose of Old Parts in Appropriate		
	Manner		
☐ Information Only	☐ No Parts Required		
Action	Distribution		
☐ Mandatory – All Affected Tools	☐ Brooks Field Service, Support, Repair		
\square Recommended – Check with Customer	☐ Brooks and OEMs		
	☑ Brooks, OEMs, and End Users		
\square No Action Required	☐ Brooks and Specific Groups/OEMs/End		
	Users		
Reason	Billing		
	⊠ Retrofit – no charge		
☐ Software Issue	☐ Upgrade – billable		
☐ Operation Issue	☐ Standard Warranty		
☐ Maintenance Issue	\square Other Warranty, see explanation below		
\square Information or Documentation	☐ No Billing		
☐ Other			

Purpose of this TSB

This Technical Service Bulletin (TSB) addresses potential hardware failure of the front and bottom-facing LED PCBAs or IntelliGuide vision processor of the IntelliGuide v23 and v60 products.

Affected Product(s)

Part Numbers: PF0V-MA-00400-4, PF0V-MA-00400-7, PF0V-MA-00400-12, PF0V-MA-0040X-4, PF0V-MA-0040X-7, PF0V-MA-0040X-12, PF30-MA-0040X-4-V23, PF30-MA-0040X-7-V23, PF30-MA-0040X-12-V23, PF30-MA-0040X-4-V60, PF30-MA-0040X-7-V60, PF30-MA-0040X-12-V60, PFC0-MA-00010-05-V23, PFC0-MA-00010-10-V23, PFC0-MA-00010-10-V23, PFC0-MA-00010-10-V60, PFC0-MA-00010-10-V

TSB-1311

IntelliGuide v23/ v60 LED PCBA Replacement

Rev A

MA-00010-14-V60, 397209, 601388, PF0V-MA-00001-1, PF3V-MA-00001-1, PF0V-MA-C1001-1, PF3V-MA-C1001-1, PF0V-MA-00001-2, PF3V-MA-00001-2

Cause

The failure may occur upon powering up the IntelliGuide vision gripper or turning the LEDs on.

The gripper functions (position and force control) of the IntelliGuide v23 and v60 grippers remain functional even after the mentioned failure modes.

Resolution

The LED PCBA has been updated from Rev B01 (capacitor C5 with 35V rating) to Rev B02 (capacitor C5 upgraded to 50V rating). Brooks tested >40,000 power cycles without failure.

Field-replaceable IntelliGuide cover subassembly will be provided to customers upon failure. The subassembly includes the IntelliGuide vision processor, cameras (qty 2), and Rev B02 LED boards (qty 2) and the cover.




Figure 1: Example label applied to existing IntelliGuide vision grippers, with part and serial numbers




Figure 2: Example label applied to new, field-replaceable subassemblies, with revision and serial numbers



TSB-1311

IntelliGuide v23/v60 LED PCBA Replacement

Rev A

Replacement options:

- 1. Replace existing IntelliGuide cover subassembly with new subassembly
 - Requires compatibility check between calibration model on new IntelliGuide vision processor and runtime library

If users experience a failure as described above, issue a replacement request to support preciseflex@brooks.com along with serial number and part number of PreciseFlex robot.

Replacement procedure is provided below.

Additional Warranty Information

Products beyond their initial warranty period with the affected IntelliGuide vision gripper hardware failure will be eligible for replacement parts (IntelliGuide vision gripper subassembly) at no cost. This additional warranty period to be up to one (1) year beyond the original warranty.

TSB-1311

IntelliGuide v23/ v60 LED PCBA Replacement

Rev A

Tools Required


Quantity	Description
1	M1.3 Hex Driver
2	M2 Hex Driver

Materials Required

One of the following:

Part Number	Quantity	Description
610398	1	ASSY,COVER,GRIPPER,P009-WH14 PC,23N WITH VISION
610810	1	ASSY,COVER,GRIPPER,P009-WH14 PC,60N WITH VISION


Procedure - Replacement



TSB-1311

IntelliGuide v23/ v60 LED PCBA Replacement

Rev A




3. If possible lower the robot arm closer to a working surface by pressing on the brake release button underneath the inner link (brake release button on PreciseFlex 400 robot shown for reference)



TSB-1311

IntelliGuide v23/ v60 LED PCBA Replacement

Rev A




TSB-1311

IntelliGuide v23/ v60 LED PCBA Replacement

Rev A

Step **Action** 6. Loosen the 4x M2.5-6 SHCS with an M2 hex driver and lift the IntelliGuide vision processor board up enough to clear connector A from the sheet metal tab

7. Disconnect the following slip-ring plugs from the IntelliGuide vision processor connectors




- A: 24 VDC Power Input (6 pin)
- B: Ethernet (4 pin)
- C: Digital Output (5 pin)


TSB-1311

IntelliGuide v23/ v60 LED PCBA Replacement

Rev A



9. With new subassembly (PN 610398 OR PN 610810), install the following slip-ring plugs into the IntelliGuide vision processor connectors. Route the cables for plugs A and C under the



board as shown. Zip tie the cables from plugs A, B and C together as shown. Tighten the 4x M2.5-6 SHCS

A: 24 VDC Power Input (6 pin)


B: Ethernet (4 pin)

C: Digital Output (5 pin)

TSB-1311

IntelliGuide v23/ v60 LED PCBA Replacement

Rev A



Revision History:

Revision	ECO	Date	Action	Author
Α	EC158080	9/25/2025	Initial Release	Dalton Dodge